Work Orde	er ID 83621 7:52 PM		*83621*								Page 1				
Item ID: Revision ID:	D412-742-043			Accept	*N900	040	100)*	Setup	Start	*N	S1*			
Item Name:	Replacement Float Skidtube									Stop	*N	S2*			
Start Date: Required Date: Reference:	20/04/2012 Start Qty: 04/05/2012 Req'd Qty:		*1* *1*		Cust Item I Customer:	D:	,				,				
Approvals:	Process Plan: _MLJ	Date:	1 1	ZO Tooling: SPC (Y/N):	40.	nte:			Run	Start Stop	*N *N	R1* R2*			
Sequence ID/ Work Center II	Operation Description			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	t Rej Qty		Reject Number	Insp. Stamp			
Draw Nbr	Revision Nbr														
D3391	I			•											
100		·	· · · · · · · · · · · · · · · · · · ·	0.00											
100 DC Document Control		no 412-742-043 is a ^v		*	CHG005				<u> </u>						

Dart Ag	rospace	Ltd								4
W/O: ,			W	ORK ORDER C	HANGES			,		
DATE	STEP	PRO	CEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
	·									
		,	,	-						
Part No);	PAR #:	Fault Cate	gory:	NC	R: Yes	No DQ	A:	Date: _	
•	R	esolution:	Dispositio	n:	QA	: N/C (losed:	•	Date: _	
NCR:		V	VORK ORD	ER NON-CONF	ORMANCI	E (NC	R)	···- · · · · · · · · · · · · · · · · ·		
		Description of NC		Corrective Action	Section B	.	Vorifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Desc Chief Eng		Sign Date	& Sect	ion C	Chief Eng	QC Inspector
			,							
J	16									

83621

Page 2

April-20-12 2:27:52 PM

												x
Item ID: Revision ID:	D412-742-04	43		Accept	*	N 900	040	100)* s	Setup Star	1.71	S1*
Item Name:	Replacement I	Float Skidtube								Stop	*N	S2*
Start Date: Required Date:	20/04/2012 04/05/2012	Start Qty: 1.00 Req'd Qty: 1.00		*1* *1*		Cust Item I	ID:					
Reference:			-	•								
Approvals:	Process Pla		Date:	Toolin		D			F	Run Star Stoj	1/1	R1*
	QC:		Date:	SPC (Y/N):		ate:	·········	r .	210	*N	R2*
Sequence ID/ Work Center II)	Operation Description		Rui	Up/ n Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
110 *110* HandFinish		HandFinishing Memo		0.00	·				1 1	4	Il 1	105/2
Hand Finishing		1-Install tube 241/291. Er 7/16" "T" Pi A/RSikaflex Expiry date:	nsure tube end ns. -241/-291 / 13/67 urplates as per	d seal them all the way a s line-up with saddle hol	round using Sikafle les for proper alignr at plastic washers a	nent. using re against		\ \ 		~.		•.
		/ A/RSikaflex		of tube ,hand tighten or <u>시시 (기 나</u> 이역 —	nly bolts with no sil	kaflex.						
		/ MEK degrea	posed hardwa	are with LPS Procyon. R	demove any excess o	off with						() . () .

Dart Ae	rospace I	Ltd								•
W/O: -			WO	RK ORDER CHANG	ES					
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву		Date G	ty Chief	roval Eng / I Mgr	Approva QC Inspecto
Part No) :	PAR #:	Fault Categ	jory:	NCR: Yes	s N	o DQA: _	Da	 ate: _	
	Res	solution:	Disposition	1:	_ QA: N/C	Clos	sed:	Da	ate: _	
NCR:		•	WORK ORDE	R NON-CONFORMA	NCE (NC	R)				
DATE	STEP	Description of NC		Corrective Action Section		<u> </u>	Verification	on App	roval	Approva
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		Section C		f Eng	QC Inspecto
				·						
		•								
										,
	1						<u> </u>			

Work Ord <i>April-20-12 2:2</i>		621	*83621*							Pag				
Item ID: Revision ID: Item Name: Start Date: Required Date: Reference:	D412-742-04 Replacement F 20/04/2012 04/05/2012		*1* *1*	Accept	*N900040 Cust Item ID: Customer:		100)*	Setup	Start Stop		S1* S2*		
Approvals:		n:		_		te:			Run	Start Stop		R1* R2*		
Sequence ID/ Work Center II 120 *120 CONTROL QC Quality Control	D	Operation Description QC5- Inspect part compl Memo	eteness to step on W/O	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp		
130 Packaging Packaging		Packaging Memo Identify and Location: PPP Rev:	pack for shipping as per P	0.00 PPP D412-742-043	\$1082					<u> </u>	15130	P. P		
*140 *140* QC Quality Control		QC21- Final Inspection - Memo	Work Order Release	0.00)	4W /	121 MK 12-0	5-30		

Dart Ae	rospace	Ltd							•
W/O:			WC	RK ORDER CHANGES	,		į	,	
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
						l . I			
					.		 ;		
	:								
·							<u>.</u>		
Part No):	PAR #:	Fault Cate	gory: f	NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Disposition	n: (A: NC	Closed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NC	R)			
DATE	OTED	Description of NC		Corrective Action Section E		Verifi	cation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspecto
-	. ^							:	
ŀ		4							

Picklist Print

April-20-12 2:27:56 PM

Work Order ID: 83621

83621

Parent Item:

D412-742-043

D412-742-043

Parent Item Name: Replacement Float Skidtube

Start Date: 20/04/2012

Required Date: 04/05/2012

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev A 05.10.13 New Issue

KJ/JLM

IPP Rev 06.02.13 ECN 773 dwg @, rev.D EC

JLM

IPP Rev:C 07-05-28

As per Rev F

IPP Rev:D 07-12-04 ECN 1072

DD verified by:JLM

IPP Rev:E 08-09-08 ecn 08-510 DD verified by:EC

IPP Rev:F

11.11.01 as per DSI9517 REV.B DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Status Issued
D3391-021	-,3-	Manufactured	No			110	Each	0.0000	1	1 .		
D3391-02 Fwd Tube Assembly	21								**	13823	360 (v) Il 12/05/2
D3391-023		Manufactured	No			110	Each	1.0000	1	1		
D3391-02 Mid Tube Assembly	23								**	3836	23 C	(1) JU 12/05/2
				Location		Loc	<u>Oty</u>	Loc Code				
				FP			2					
					81105		1		•••		_	
				GA			-1		_		_	
D3391-025		Manufactured	No			110	Each	1.0000	1	1 ·		
D3391-02 Aft Tube Assembly	25								**	383(032(11) Juniosla
				Location		Loc	<u>Oty</u>	Loc Code				
				FP001			1		_		_	
					81111		1				_	

Page 1

Dart Ae	rospace	e Ltd									3
W/O:		<u></u>	WC	RK ORDER CHA	NGES						
DATE	STEP	PROC	CEDURE CHAI	NGE		Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
									,		
									5		
Part No):	PAR #:	_ Fault Cate	gory:	NC	R: Yes	s N	o DQ/	7 :	Date: _	
<i>:</i>	R	esolution:	_ Disposition	n:	QA	: N/C (Clos	ed:		Date: _	
NCR:		W	ORK ORDE	R NON-CONFOR	RMANCE	E (NC	R)				
5475	OTED	Description of NC		Section B			Verific	ation	Approval	Approva	
DATE	STEP	Section A	Initial Chief Eng	Action Descript Chief Eng	ion 	Sign Dat		Section C		Chief Eng	QC Inspecto
									<u> </u>		
,										·	
							· · · · · · · ·		,		
							!				

Picklist Prin	1
---------------	---

Page 2

April-20-12 2:27:56 PM

Work Order ID: 83621

D412-742-043

Parent Item Name: Replacement Float Skidtube

83621

D412-742-043

Start Date: 20/04/2012

Required Date: 04/05/2012

Start Qty: 1.00

**

**

Required Oty: 1.00

AN3C4A

Parent Item:

AN3C4A

AN3C6A

No

No

Purchased

Purchased

110

Each

2,292,000

24

24

12/05/23

Location Loc Qty ST350 2292 120187 1226 120521 28 120769 38 121205 1000 110 Each

425.0000

17121556

Loc Code

x 24

10

H 12/05/23

AN3C6A BOLT

Location	Loc Qty	Loc C
FP001	1	
111982	1	
ST351	424	
111982	2	
116419	23	
116549	2	
116704	. 12	
117619	10	
117688	1	
117872	5	
118422	13	
119449	21	
120423	2	

332

ode

XIO

120693

Dart Ae	rospace	e Ltd								i.
W/O:	:	. 1	WO	RK ORDER CHANG	ES					<u> </u>
DATE	STEP	PR	OCEDURE CHAP	IGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								-		
	<u> </u>								,,,,,,,	
Part No) :	PAR #:	Fault Categ	ory:	_ NCR: Ye	es N	o DQ	A:	Date: _	
	R	esolution:	Disposition	i	_ QA: N/C	Çlos	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	CR)					
		Description of NC		on B		Verific	ation	Approval	Approvai	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Secti		Chief Eng	QC Inspecto
-										
						<u> </u>				
		·			1				·	
-										
1					1	1	1			

April-20-12 2:27:56 PM

Work Order ID: 83621		*8:	3621*				•	
Parent Item: D412-742-04 Parent Item Name: Replacem	enent Float Skidtube		412-742-0)43*			20/04/2012	
Tarent Hem Name. Replacen	ioni i loai skididoc						ate: 20/04/2012 Oty: 1.00	Required Date: 04/05/2012 Required Qty: 1.00
AN3C7A	Purchased	No		110	Each	140.0000	4 4	
AN3C7A						**	16	12/05/23
			Location	La	oc Oty	Loc Code		
			ST351		140	M121541		
			113149 116169		14 1			
			117313		10			
			117619		12			•
			117688 119749		6 1			
			120731		46			
			121185		50			
AN960C10L NAS1	149C0332 Purchased	No		110	Each	0.0000	38 38	
*AN960C101 *					15114	509 **	(X38) H	12/06/23
D4095-041	Manufactured	No		110	Each	3.0000	1 1	
D4095-041 Wearplate Assembly						**	4/	12/05/27
			Location	Lo	c Qty	Loc Code		
			FP001		3	B81623		
D4005 040			78996		3	_		
D4095-043	Manufactured	No		110	Each	4.0000	1 1	,
D4095-043 Wearplate Assembly						**	Ju	1 1105/23
•	41		Location	Lo	c Qty	Loc Code		
			FP001		4	1761		
			78995		4	1381624		
								•

Dart Ae	rospace	e Ltd							•
W/O:		,							
DATE	STEP	PR	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
·									
Part No: PAR				ory:	NCR: Yes	No D	QA:	Date: _	
	Resolution:		Disposition		_ QA: N/C	Closed: _	· · · <u>·</u>	Date: _	
NCR:		· · · · · · · · · · · · · · · · · · ·	WORK ORDE	R NON-CONFORMA	NCE (NC	R)		-	
		Description of NC	Description of NC Corrective Acti			Veri	fication .	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	1& Sec	ction C	Chief Eng	QC inspecto
	·								

Picklist Print

April-20-12 2:27:56 PM

Page 4

Work Order ID: 83621

83621

Parent Item:

D412-742-043 Parent Item Name: Replacement Float Skidtube *D412-742-043*

Start Date: 20/04/2012

Required Date: 04/05/2012

Start Qty: 1.00

Required Qty: 1.00

D4095-045

Manufactured

110

Each


16.0000 **

D4095-045

Wearplate Assembly

<u>Location</u>	Loc Qty	Loc Code	
FP	15		
81625	15		<u> </u>
FP001	1		
77737	1		


		•	
* *			
Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect	
No DQA:	Date: _		
Closed: Date:			
Verification	Approval	Approva	
Section C	Chief Eng	QC Inspect	
:			
V(o DQA:	Date Qty Chief Eng / Prod Mgr Date: Date: Date: Verification Approval	



Dart Aerospace L	_td
------------------	-----

W/O:			ES					
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							_	
Part No:		PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQA: Date:		
Resolution:			Dispositi	on:	_ QA: N/C Cl	osed:	Date: _	
NCR:			WORK ORE	DER NON-CONFORM	ANCE (NCR)		
DATE	STEP	Description of NC	Corrective Action S Initial Action Description		tion B Sign &	Verification	Approval	Approval QC Inspector
		Section A	Chief Eng	Chief Eng	Date	Section C	Chief Eng	QC Inspector
-								
		1	1		1 1	1	i	1

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



D3391-043 FLOAT SKIDTUBE ASSEMBLY PARTS LIST

-043	PARI NUMBER	DESCRIPTION
X	D3391-043	FLOAT SKIDTUBE ASSEMBLY
	D3391-021	
		FWD TUBE ASSEMBLY
_ 1	D3391-023	MID TUBE ASSEMBLY
t	D3391-025	AFT TUBE ASSEMBLY
2	D3591-1	BUSHING
1	D4095-041	WEARSHOE
1_	D4095-043	WEARSHOE
1	D4095-045	WEARSHOE
1	D4095-047	WEARPAD
1	D4095-049	WEARPAD
1	D4095-051	WEARSHOE
24	AN3C4A	BOLT
		1000

BOLT

WASHER

GENERAL NOTES

CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3 COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS OFF POWDER COATING WITH MEK DEGREASER.

TOLERANCES: PER DART QSI 018 UNLESS, OTHERWISE NOTED

UNITS: INCHES UNLESS OTHERWISE NOTED

USE DART DRILL TEMPLATE DT8217 TO LOCATE AND DRILL Ø0.297 SIZE HOLES FOR WEARSHOE INSERTS. C'BORE AS NOTED AND INSTALL INSERTS EXCEPT WHERE INDICATED.

FIT D4095-041 TO SKIDTUBE WITH D2571 AND D2572 SADDLES INSTALLED WITH APPROPRIATE HARDWARE AND SPACERS IN FORWARD AND AFT HOLES AND TRANSFER DRILL Ø0.50 HOLES FROM SADDLE TO D4095-041

FIT D4095-043 TO SKIDTUBE WITH D2571 AND D2572 SADDLES INSTALLED WITH THE APPROPRIATE HARDWARE AND SPACERS IN FORWARD AND AFT HOLES AND TRANSFER DRILL Ø0.50 HOLES FROM SADDLE TO D4095-043

DESIGN	PH	DART AEROSPACE USA, INC				
DRAWN	XDF	KENT, WA				
CHECKED		DRAWING NO.	REV. I			
MFG. APPR.	Z	D3391	SHEET 2 OF 8			
APPROVED	14	TITLE	SCALE			
DE APPR.	4	412 FLOAT SKIDTUBE	NTS			
DATE 11.1	0.13	COPYRIGHT © 2005 BY DART AEROSPACE USA, INC his occurrent is retained and controlled use a surprise on the express condition that it is not to the use for any mercise on cores on communication to have one reason without				

AN3C6A

AN3C7A


Đ

С


В

Dart Aerospace Ltd W/O: **WORK ORDER CHANGES Approval Approval** DATE STEP **PROCEDURE CHANGE** By **Date** Qty Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ___ Date: ____ Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ____


NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B			Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	QC Inspector			
						<u> </u>					
							,				




Dart Ae	rospace	Ltd							,
W/O:			WO	RK ORDER CHANGES	3			•	
DATE	STEP				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes	No DC	A:	Date: _	
	Re	esolution:	Disposition:					Date: _	
NCR:			WORK ORDE	ER NON-CONFORMAN	ICE (NC	R)			
DATE	CTED	Description of NC	Corrective Action Section B			Verif	ication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sec	tion C	Chief Eng	




Dart Aerospace Ltd W/O: **WORK ORDER CHANGES Approval Approval STEP PROCEDURE CHANGE** Qty DATE By Date Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: _____ QA: N/C Closed: ____ Date: _____ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification **Approval Approval** DATE **STEP** Sign & **Action Description** Initial Section A Chief Eng Section C QC Inspector Date Chief Eng Chief Eng




Dart Ae	rospace L	td							•
W/O:			WO	RK ORDER CHANGES	3				
DATE	STEP	PROCEDURE CHANGE			Ву	Da	te Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
Part No	<u> </u>	PAR #:	Fault Cated	lorv.	NCR: Yes	No	DQA:	Date:	
Resolution:									
NCR:		-	WORK ORDE	R NON-CONFORMAN	CE (NC	R)			
	0777	Description of NC	Corrective Action Section B			V	erification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	&	Section C	Chief Eng	QC Inspecto
•							-		
							•		



Dart Ae	rospace	Ltd				-				6 , d
W/O:			WORK ORDER CHANGES							
DATE	STEP	PR	OCEDURE CHAN	IGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
	·									
Part No		PAR #:								
-	Re	solution:	Disposition	:	QA: N/C	Clo	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	IANCE (N	CR				
		Description of NC	Corrective Action S		Section B		Verifi	ration	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		Verification Ap Section C		QC Inspecto
	-			-						
				ι				· ·		



Dart Ae	rospacé	e Ltd							•	
W/O:			WC	RK ORDER CHAN	GES		····································			
DATE	STÉP	PROCEDURE CHANGE By			Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto		
	:	,								
Part No):	PAR #:	Fault Cate	jory:	NCR: Ye	s No DO	QA:	Date: _		
	R	esolution:	Disposition	Disposition: QA: N/C (Closed: Date:			
NCR:			WORK ORD	ER NON-CONFORM	IANCE (NO	CR)				
		Description of NC		Corrective Action Se	ction B	Veri	Verification A		Approva	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigı Da	1 & Se	ction C	Approval Chief Eng	QC Inspecto	
	:									



Dart Aerospace Ltd							.*			٠ ۾ ھ
W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCI	DURE CHANGE			Ву	Date	Qty	Qty Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•	-				v .	
Part No		PAR #:								
	R	esolution:							Date: _	·
NCR:	·	W	ORK ORD	ER NON-CONFORMA	NCE	(NC	R)			
DATE	STEP	Description of NC	Corrective Action Section		n B	0:	Verific		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign Date		on C	Chief Eng	QC Inspector
					<u> </u>	,				
•		ic.								